Inspection Report

Provided by:



NE-HomeInspections.com

NE ExpediteHomeinspections LLC

Northeast Expedite Home Inspections LLC

Inspector: David DeVries Phone: 603-520-9624 Email: dave.nehomeinspections@gmail.com David DeVries License # 360 160 Center Street Wolfeboro, New Hampshire 03894 Property Address:

Brookfield, New Hampshire 03872



Table Of Contents:

Section name: Section number: **Report Information** 1 **Report Summary Page** 2 Grounds 3 Exterior 4 Roofing 5 Heating - Air 6 Electrical 7 Plumbing 8 Interiors 9 Kitchen 10 Bath(s) 11 **Basement** 12 Garage - Laundry Foundation - Crawl Space 14

1 Report Information

Client Information

Client Name

Property Information

Approximate Year Built	1998
Approximate Square Footage	2900
Number of Bedroom	4
Number of Bath	3
Direction House Faces	East
Inspection Information	
Inspection Date	June 5, 2017
Inspection Time	12:30pm - 3:0

Outside Temperature 56

Price for Inspection

Weather Conditions

WITHIN THE SCOPE OF THE INSPECTION

The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See Standards of Practice for a detailed description of the scope of inspection.

3:00pm

Rain

Exterior:

Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

Interior:

Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other

Northeast Expedite Home Inspections LLC

Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible) (as to evidence of water damage and general condition.)

- The scope of the inspection is limited to the description and the general condition of the above systems.

OUTSIDE THE SCOPE OF THE INSPECTION

-Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection.
-The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;

- Building code or zoning ordinance violations - Thermostatic or time clock controls or Low Voltage wiring systems - Geological stability or soils conditions - Water softener or water purifier systems or solar heating systems - Structural stability or engineering analysis - Saunas, steam baths, or fixtures and equipment - Building value appraisal or cost estimates - Pools or spa bodies or sprinkler systems and underground piping - Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters - Furnace heat exchanger, freestanding appliances, security alarms or personal property - Specific components noted as being excluded on the individual system inspection form - Adequacy or efficiency of any system or component - Prediction of life expectancy of any item.

- The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

CONFIDENTIAL REPORT

-The written report to be prepared by the Inspector shall be considered the final and exclusive findings of the Inspector/Inspection Company regarding the home inspection at the Inspection Address. The inspection report to be prepared for the Client is solely and exclusively for the Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person with the exception of the seller and/or the real estate agents directly involved in this transaction. Client(s) or the inspector may distribute copies of the inspection report to the seller and real estate agents directly involved in this transaction, but neither the seller nor the real estate agent are intended beneficiaries of this Agreement or the inspection report. Client agrees to indemnify, defend, and hold the Inspector/inspection Company harmless from any third party claims arising out of the Client's or Inspectors distribution of the inspection report.

DISPUTES

• Client understands and agrees that the Inspector/Inspection Company is not an insurer, that the price paid for the subject inspection and report is based solely on the service provided. Client also agrees that any claim of failure in the accuracy of the report shall be reported to the Inspector/Inspection Company within five business days of discovery and that failure to notify the inspector within that time period shall constitute a waiver of any and all claims. The Inspector/Inspection Company shall have five business days to respond to the claim. If the Inspector/Inspection Company fails to satisfy the claim, liability shall be limited to a refund of the price paid for the Inspection and Report.

Northeast Expedite Home Inspections LLC

Definition of conditions:

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.

S = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

2 Report Summary Page

This is only a summary of the inspection report and is not a complete list of discrepancies. Please read each section for comments and suggestions. I did not observe any visual evidence of pests, wood destroying insects, mildew or mold type organisms.

Section	Condition#	Comment
Interiors	37	Appeared to be in serviceable condition at time of inspection. Always have a chimney professional inspect chimney annually. Wood insert/stove not inspected. Flue was not accessible and not inspected.
Bath(s)	56	Appeared to be in serviceable condition at time of inspection. Interior light fixture was installed above the shower or tub. Inspector cannot determine if this an approved fixture for the shower.
Basement	62	A tripping hazard was observed at the bottom of stairs. Recommend repair for safety.
Basement	68	Missing receptacle or switch covers were observed. Recommend covers be installed for safety.
Garage - Laundry	76	The interior doors appeared to be in serviceable condition at the time of the inspection. A transition piece is needed where stairs meet the entrance.
Garage - Laundry	79	Appeared to be in serviceable condition at time of inspection. Cover missing from outlet. Recommend installing cover and GFIC outlet.

Grading

Grading Slope


The site is flat.


1) Grading Conditions



Grading of the soil near the foundation appears to be in serviceable condition.

3 Grounds





Driveways - Sidewalks - Walkways


Driveway Material

Asphalt

2) Driveway Conditions



The driveway appeared to be in serviceable condition at the time of the inspection. Common cracks were observed in the driveway.








3) Sidewalk Conditions



The visible areas of the sidewalk appeared to be in serviceable condition at the time of the inspection.



Exterior Walls

Structure Type

Wood frame

Exterior Wall Covering

The visible and accessible areas of the exterior siding material are vinyl.


6) Exterior Wall Conditions



The visible and accessible portions of the exterior wall coverings appeared to be in serviceable condition at the time of the inspection.







Exterior Windows - Doors

Window Type	Double Hung
-------------	-------------

Window Material Vinyl

7) Window Conditions



Windows appeared to be in good condition a time of inspection.







8) Exterior Door Conditions



The door(s) appeared to be in serviceable condition at the time of the inspection.

Exterior Water Faucet(s)

9) Faucet Conditions



The hose faucets appeared to be in serviceable condition at the time of the inspection. These should be drained prior to freezing temperatures.



Chimney

10) Chimney Conditions



Recommend inspection by a qualified chimney specialist prior to using,



	5 Roofing
Roof Covering	
Method of Inspection	The roof was inspected by viewing with high power binoculars.
Roof Style	Gable
Roof Covering Material	Asphalt shingles.
Number of Layers	One
11) Roof Covering Condition	AS The roof covering shows normal wear for its age and appeared to be in serviceable condition at the time of the inspection.

12) Flashing Conditions




The exposed flashings appeared to be in serviceable condition at the time of inspection.





Attic Area


Attic Access	Closet Cubby
Method of Inspection	Viewed from ladder.
Roof Frame Type	The roof framing is constructed with rafter framing.
13) Attic Conditions	AS The visible and accessible portions of the attic appeared to be in serviceable condition at the time of the inspection.





Attic Ventilation Type	Gable Vents, Ridge Vents, Soffit vents
Attic Ventilation Conditions	Minimal ventilation was provided to the attic area. This may not be sufficient to move air through the attic properly. Recommend installing additional vents.
Attic Insulation Type	Batt Insulation
14) Attic Insulation Conditions	AS The attic has fiberglass batt insulation. The approximate depth of the insulation is 8 to 10 inches. This appears adequate.







Basement

6 Heating - Air

Heating

Heating Type

Hot Water - Radiant

Energy Source

Oil

15) Unit Conditions

AS

The heating system was operational at time of inspection. This is not an indication of future operation or condition. There is a stand alone unit above garage that was not inspected. Un plugged.



Distribution Type


Radiant & Baseboard

16) Distribution Conditions



The visible and accessible areas of the distribution system appeared to be in serviceable condition at the time of inspection.









17) Ventilation Conditions



The visible and accessible portion of the venting flue appeared to be in serviceable condition at the time of the inspection.



18) Thermostat Condition



The normal operating controls appeared to be serviceable at the time of the inspection.







7 Electrical

Service Drop - Weatherhead

Electrical Service	Aluminum
Material	

Number of Conductors Three


19) Electrical Service Conditions AS

The main service entry appeared to be in serviceable condition at the time of inspection.



Main Electrical Panel

Main Disconnect Location	At Main Panel
Electric Panel Location	The main electric panel is located at the basement.
Panel Amperage Rating	200
Circuit Protection Type	Breakers
20) Wiring Methods	AS The main power cable is aluminum. The branch cables are copper.



21) Electrical Panel Conditions



The main panel appeared to be in serviceable condition at the time of the inspection.





Electrical Sub panel

Sub panel Location

22) Sub panel Conditions



A sub panel is located at the garage.

The sub panel appeared to be in serviceable condition at the time of inspection.





Water Main Line

Main Shutoff Location The main valve is located at the basement.

Main Line Material

The visible material of the main line / pipe appears to be plastic.

8 Plumbing

23) Main Line & Valve Conditions



The visible portion of the main pipe and valve appeared to be in serviceable condition at the time of the inspection.





Water Supply Lines

Supply Line Material

24) Supply Line Conditions

Drain - Waste Lines

Drain Line Material

25) Drain Line Conditions



The visible portions of the supply lines appeared to be in serviceable condition at the time of inspection. All of the supply lines were not fully visible or accessible at the time of the inspection.


The visible portions of the waste lines are plastic.

The visible material used for the supply lines is copper.



The visible portions of the waste lines appeared to be in serviceable condition at the time of inspection. All of the waste lines were not fully visible or accessible at the time of the inspection.







Water Heater(s)

Water Heater Type

Super Store

Water Heater Location

26) Water Heater Conditions



Boiler

The water heater was operable at the time of inspection. This does not however guarantee future performance, operation, or condition.



	9 Interiors
s - Ceilings - Floors	
7) Wall Conditions	AS The general condition of the walls appeared to be in serviceable condition at the time of the inspection.
8) Ceiling Conditions	AS The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.





29) Floor Conditions

AS

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.







30) Heat Source Conditions



Appeared to be in serviceable condition at time of inspection.

Windows - Doors

31) Interior Window Conditions



The sample of windows tested were operational at the time of the inspection.











32) Interior Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

33) Electrical Conditions

34) Lighting Conditions

AS	

AS

Appeared to be in serviceable condition at time of inspection.


Appeared to be in serviceable condition at time of inspection.

35) Ceiling Fan Conditions




Appeared to be in serviceable condition at time of inspection.





36) Smoke Detector Conditions



Appeared to be in serviceable condition at time of inspection.









Fireplace

Fireplace Location

A fireplace w/wood insert is located at the living room.

Fireplace materials

37) Fireplace Conditions



The fireplace is mason built.

Appeared to be in serviceable condition at time of inspection. Always have a chimney professional inspect chimney annually. Wood insert/stove not inspected. Flue was not accessible and not inspected.



10 Kitchen

Walls - Ceilings - Floors

- **38) Wall Conditions**
- AS Tł
- The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



39) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.







The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



Windows - Doors

41) Kitchen Window Conditions



The sample of windows tested were operational at the time of the inspection.


Electrical Conditions

42) Electrical Conditions



Appeared to be in serviceable condition at time of inspection.







43) Lighting Conditions



Appeared to be in serviceable condition at time of inspection.

Kitchen Sink - Counter tops - Cabinets

44) Counter Conditions



The visible portion kitchen counters appeared to be in serviceable condition at the time of the inspection.



45) Cabinet Conditions



The kitchen cabinets appeared to be in serviceable condition at the time of inspection.







46) Sink Plumbing Conditions



Appeared to be in serviceable condition at time of inspection. There is a filtering system on the drinking water. Check with seller for details.









Appliances

Stove - Range Type

The range and oven is electric.

47) Stove - Range Condition



The oven and range was in operational condition at the time of the inspection. This does not however guarantee future conditions after the time of inspection.



48) Hood Fan Conditions



The fan / hood and light were in operational condition at the time of the inspection.

49) Dishwasher Conditions



Appeared to be in serviceable condition at time of inspection.

AS

11 Bath(s)

Walls - Ceilings - Floors

- 50) Wall Conditions
- The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



51) Ceiling Conditions


AS	The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.
	condition at the time of the inspection.

52) Floor Conditions



l

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.





Windows - Doors

53) Bathroom Window Conditions

54) Bathroom Door Conditions



AS

The sample of windows tested were operational at the time of the inspection.



The interior doors appeared to be in serviceable condition at the time of the inspection.



Electrical Conditions

55) Electrical Conditions

56) Lighting Conditions


AS	

AS

Appeared to be in serviceable condition at time of inspection. Interior light fixture was installed above the shower or tub. Inspector cannot determine if this an approved fixture for the shower.

Appeared to be in serviceable condition at time of inspection.

57) Vent Fan Conditions








Bathroom Sink

58) Counter - Cabinet Conditions



Appeared to be in serviceable condition at time of inspection.



59) Sink Conditions



Appeared to be in serviceable condition at time of inspection.





Shower - Tub - Toilet


60) Shower - Tub Conditions



The bathtub, faucet, and drains appeared to be in serviceable condition.










61) Toilet Conditions



The toilet appeared to be in serviceable condition at the time of inspection in bath









64) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

65) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



Windows - Doors

66) Basement Window Conditions



The sample of windows tested were operational at the time of the inspection.





67) Basement Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.



Electrical Conditions

68) Electrical Conditions



Missing receptacle or switch covers were observed. Recommend covers be installed for safety.







69) Lighting Conditions



70) Sump Pump Conditions



The sump pump operated when tested at the time of the inspection.

This does not however guarantee future conditions or operation.



Storage Barn


71) Barn Conditions




A courtesy inspection of the barn was performed. The electric panel was not attached with screws and is missing a large number of knockout covers. This is a safety concern. Recommend repair asap. Numerous outlets were missing covers. Recommend repair asap. There was no access to the upstairs of the barn so the condition of rafters and the roof could not be accurately determined. The outer walls, shingles, floors, lighting, and doors appeared to be in serviceable condition at the time.




















































AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected 13 Garage - Laundry Walls - Ceilings - Floors The garage is attached to the house. Number of cars is two. **Garage Type** 72) Wall Conditions The general condition of the walls appeared to be in serviceable AS condition at the time of the inspection. 73) Ceiling Conditions The general condition of the ceilings appeared to be in serviceable AS condition at the time of the inspection.

74) Floor Conditions




The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



75) Window Conditions



The sample of windows tested were operational at the time of the inspection.



76) Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection. A transition piece is needed where stairs meet the entrance.




77) Vehicle Door Conditions



The vehicle door(s) appeared to be in serviceable condition at the time of the inspection.









78) Electrical Conditions



Appears Serviceable, Missing receptacle or switch covers were observed at. Recommend covers be installed for safety.



Laundry Room

79) Laundry Room Conditions



Appeared to be in serviceable condition at time of inspection. Cover missing from outlet. Recommend installing cover and GFIC outlet.





14 Foundation - Crawl Space

Foundation

Foundation Type

Foundation Material

Concrete


Basement



AS

Appeared to be in serviceable condition at time of inspection.







Flooring Structure

Flooring Support Type

Joists, Beams, Columns

81) Flooring Support Conditions



Appeared to be in serviceable condition at time of inspection.

